

MOTOR CUMMINS X2,5-G2

Kit Mantenimiento y Repuestos



DESCRIPCION	CODIGO
Filt. Aceite	230301-52
Filt.comb ff	-
Filt.comb fs	230310-52
Filt.indic.aire	-
Filt.aire 1°	230330-52
Filt.aire 2°	-
Filt.agua	-
Radiador	232861-00
Ventilador	232841-00
Caño.ent.radiad	-
Mang.ent.radiad	232861-00
Caño.sal.radiad	-
Mang.sal.radiad	232881-00
Manguera.admisión	232891-00
Acop.adm. Motor / filt	-
Alternador	232920-00
Correa alter/bomb	232931-00
Motor.de.arran	232940-00
Sol.de.parada	232951-00
Bulbo temp (medicion)	655311-00
Bulbo temp (corte)	655350-00
Bulbo.líq.ref	655352-00
Bulbo.pres.aceit	655315-00
Bomba de agua / junta	232962-00 / 232963-00
Bomba.alim.comb. / junta	232972-00
Bomba inyec.comb/ junta	232988-00 / 232989-00
Taco radiador inf	-
Taco radiador sup	-
Estira correa	-

Primer recambio recomendado: 230301-52 | 230310-52 | 230330-52



Depto. Técnico de Bounous HNOS S.A.I.M.
Av. Jorge newbery 444 (2252) Gálvez (SFE)
Tel: 03404-517610 – Fax: 03404-481609